

Section	Applicable Model/s	Subject	Bulletin No.
02	1999 Millenia	KNOCKING NOISE FROM FRONT SUSPENSION	001/00
			Issued
			06/14/00
			Revised

APPLICABLE MODEL(S)/VINS

All 1999 Millenia.

DESCRIPTION

Some vehicles may exhibit a knock/thump/clunk noise from the front suspension area when turning over bumps, driving over rough roads at slow speeds and/or when applying the brakes. The noise appears to be more noticeable during colder temperatures. Cold temperatures can cause poor sealing of the front suspension, lower arm, rear bushing, resulting in deterioration of the bushing.



Customers having this concern should have their vehicle repaired using the following procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace lower arm bushing (rear) on both sides of the vehicle. See Workshop Manual (section 02-13-5 FRONT LOWER ARM REMOVAL/INSTALLATION).

Caution

- To prevent any further noise, be sure to position the bushing so that the protrusion is facing up as shown below.



LEFT SIDE SHOWN (RIGHT SIDE SAME)

3. Verify repair.

PART(S) INFORMATION

Part Number	Description	Qty.	Notes
T001-34-460C	Lower Arm Bushing (rear)	1	---

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools / equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Consumers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, consumers should contact their nearest authorized Mazda dealership.

Number: 02 - 001/00	Date Issued: 06/14/00	Revised:
---------------------	-----------------------	----------

WARRANTY INFORMATION

Note

- This information applies to verified customer complaints on vehicles covered under normal warranty. Refer to the SRT microfiche for warranty term information.

Warranty Type	A
Symptom Code	82
Damage Code	9E
Part Number Main Cause	See PART(S) INFORMATION
Quantity	2
Operation Number / Labor Hours	R0107BRX / 2.2