

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990



Category T	Applicable Model/s 1995-96 Millenia	Subject HEADLIGHT AIMING SERVICE POINT	Bulletin No. 001/96 Issued 01/23/96 Revised
---------------	---	---	---


APPLICABLE MODELS/VINS

All 1995-96 Millenia model vehicles.

DESCRIPTION

After adjusting the headlight aim, confirm that the drain tube is not kinked. These tubes are located around the headlight adjustment screws and may become kinked when the screwdriver is removed.

Service Managers should place a copy of this bulletin in the beginning of section T in the workshop manual.



IMPORTANT: Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature _____

Service Manager

Signature _____

Parts Manager

060017